

TRANSMITTAL

TO: Tom Pridgen

RE: Updates for Website

FROM: Mike Davis

Type of Update:

New Criteria

Addendum

Lessons Learned


DATE: December 20, 2006

I am sending you Attached
 Under Separate Cover
 Included


The following item(s) are for review and concurrence:

COPIES	DATE	No. of Sheets	DESCRIPTION
1	12/20	5	Lessons Learned from Design Errors or Omissions

REMARKS: The attached represents Lessons Learned from construction projects that have had repetitive problems or "big ticket" claims. These items will be added to the Design website under the Lessons Learned button.

Concurrence: 
Michael Davis, P.E., Senior Program Manager

12/20/06
Date

Concurrence: 
Thomas Pridgen, P.E., Assistant Turnpike Design Engineer

12/20/2006
Date

Existing rip-rap was not shown in the plans

The existing articulated rip rap along the Canal was not shown on the plans. It was in conflict with the construction of the noise wall footings and gabions and had to be removed and replaced.

Lessons Learned: Designer must conduct site survey prior to design. CEI must review plans in the field prior to construction to make sure field conditions have not changed.