

TRANSMITTAL

TO: Tom Pridgen

RE: Updates for Website

FROM: Mike Davis

Type of Update:

New Criteria

Addendum

Lessons Learned


DATE: December 20, 2006

I am sending you Attached
 Under Separate Cover
 Included


The following item(s) are for review and concurrence:

COPIES	DATE	No. of Sheets	DESCRIPTION
1	12/20	5	Lessons Learned from Design Errors or Omissions

REMARKS: The attached represents Lessons Learned from construction projects that have had repetitive problems or "big ticket" claims. These items will be added to the Design website under the Lessons Learned button.

Concurrence: 
Michael Davis, P.E., Senior Program Manager

12/20/06
Date

Concurrence: 
Thomas Pridgen, P.E., Assistant Turnpike Design Engineer

12/20/2006
Date

ROW shown and labeled twice along ramp

Plan sheets showed two limited access Right of Way lines parallel to each other. The Contractor laid utilities and installed a fence at the wrong location. The designer revised plans, but costs to relocate were premium and due to designer error.

Lesson Learned: *Designers must insure ROW is shown correctly on the plans.*